

Compression Shower Valves 1949 to Present

NOTE: Complete valve assemblies are not shown. Only those parts reflecting basic design changes are illustrated.



128-011 Handle "Hot"
128-012 Handle "Cold"



119-008 Valve Stem

125-001L
Bibb Washer



160-001 or
160-146 Screw

VALVE ASSEMBLY NO. S02-018

Furnished from 1949 to 1963.
Only the 125-001L & 160-146 are still available.



128-021 Handle



119-042 Valve Stem

125-001L
Bibb Washer



160-146
Screw


Valve Assembly S02-031 (Tempered), S0-2031A (Cold), S02-031B (Hot)

First S02-031 Series

Furnished from 1963 to 1968.
Only the 125-001L & 160-146 are still available.

REPAIR KIT NO. S45-048

CONTENTS		
Qty	Part No.	Item
1	160-146	Screw
1	125-001L	Bibb Washer
1	124-001BD	Fibre Washer
1	125-001BC	"O" Ring
1	117-002	Renewable Valve Seat
1	124-001K	Valve Body Washer




128-028 Handle



119-050 Valve Stem

125-001L
Bibb Washer



160-146
Screw

Second S02-031 Series


Furnished from 1968 to 1969.
Only the 128-028, 125-001L & 160-146 are still available.

REPAIR KIT NO. S45-048

CONTENTS		
Qty	Part No.	Item
1	160-146	Screw
1	125-001L	Bibb Washer
1	124-001BD	Fibre Washer
1	125-001BC	"O" Ring
1	117-002	Renewable Valve Seat
1	124-001K	Valve Body Washer



128-028 Handle



119-052 Valve Stem

125-001L
Bibb Washer



120-017
Valve Stem
Extension



160-146
Screw

Third S02-031 Series

Furnished since 1969.
Only the third S02-031 Services can be provided complete, either as an assembly, or as individual parts.

REPAIR KIT NO. S45-048A

CONTENTS		
Qty	Part No.	Item
1	120-017	Valve Stem Extension
1	160-146	Screw
1	125-001L	Bibb Washer
1	124-001BD	Fibre Washer
1	124-001K	Washer
1	125-001BC	"O" Ring
1	117-002	Renewable Valve Seat

Available as S21-020
valve stem assembly